



# 1 - SETTING OF THE STROKE - SINGLE MOTOR


At the first power up, it is necessary to carry out a learning of the stroke for the acquisition of the stroke length and the slowdowns. After this procedure the installation is complete. Select the functioning with a single motor:




Make sure that the board is out from any programming menus. To enter the menu, press and hold the "MENU" button for at least 1 second.




Use the "UP" and "DOWN" buttons to move inside the items of the menu. Select the item  $n̄t$ .




To enter the item, press and hold the "MENU" button for at least 1 second until the value blinks.



Use the "UP" and "DOWN" buttons to change the value.



To save the value, press and hold the "MENU" button for at least 1 second.



To quit, press briefly the "MENU" button.

**WARNING** - For a correct functioning of the system, it is absolutely indispensable the use of mechanical stops in opening and closing.









## 1.1 - EASY SETTINGS OF THE STROKE ( $L5I \neq P$ ) - SINGLE MOTOR

1.	<p>Connect the automation to the MOTOR 1 output and check to have set the <math>n̄t = 1</math>.</p> <p>Carry out a check of the menus and, if needed, customize the settings before the learning of the stroke.</p> <p>The slowdowns will be those set in the menu, with the same percentage during both opening and closing (<math>L5I \neq P</math>).</p>	
2.	<p>Unlock the automation and move it to the middle of the stroke</p> <p>Press at the same time the "UP" and "MENU" buttons for at least 5 seconds until the display shows <math>LDP</math>.</p>	
3.	<p>If the automation <b>DOESN'T MOVE</b> in opening, press the "DOWN" button to stop the learning. The display shows <math>L--</math>.</p>	
4.	<p>Press the "SS" button to restart the procedure: the automation moves in opening, at reduced speed. When the automation reaches the opening mechanical stop give a step by step command (SS). In this phase the display shows <math>LDP</math>.</p>	
5.	<p>The automation moves automatically in closing, at running speed. When the automation reaches the closing mechanical stop give a step by step command (SS). In this phase the display shows <math>LCL</math>.</p>	
6.	<p>The automation moves automatically in closing, at running speed. When the automation reaches the opening mechanical stop give a step by step command (SS). In this phase the display shows <math>LDP</math>.</p>	
7.	<p>The automation moves in closing at running speed and with the slowdowns set into the menu <math>L5I</math>.</p>	

**WARNING** - in the event of a safety device intervention, the learning is stopped and will appear on the display  $L--$ . Press the "SS" button to start again the learning from the 4th point.

ENG

## 1.2 - ADVANCED SETTINGS OF THE STROKE (L5I = P) - SINGLE MOTOR

1.	<p>Connect the automation to the MOTOR 1 output and check to have set the <math>L5I = P</math>.</p> <p>Carry out a check of the menus and, if needed, customize the settings before the learning of the stroke.</p> <p>Be sure to have set the item menu <math>L5I = P</math>.</p> <p>The slowdowns should be set during the learning procedure and the amplitudes will be independent in the two directions.</p>	
2.	<p>Unlock the automation and move it to the middle of the stroke</p> <p>Press at the same time the "UP" and "MENU" buttons for at least 5 seconds until the display shows LOP.</p>	
3.	<p>If the automation <u>DOESN'T MOVE</u> in opening, press the "DOWN" button to stop the learning. The display shows L--.</p>	
4.	<p>Press the "SS" button to restart the procedure: the automation moves in opening, at reduced speed. When the automation reaches the opening mechanical stop give a Step-by-Step command (SS). In this phase the display shows LOP.</p>	
5.	<p>The automation moves automatically in closing, at running speed. When the automation reaches the position for the beginning of the slowdown, give a Step-by-Step command (SS). In this phase the display shows LCL.</p>	
6.	<p>The automation proceeds at slowdown speed. When the automation reaches the closing mechanical stop give a Step-by-Step command (SS). In this phase the display shows LCL.</p>	
7.	<p>The automation moves automatically in opening, at running speed. When the automation reaches the position for the beginning of the slowdown, give a Step-by-Step command (SS). In this phase the display shows LOP.</p>	
8.	<p>The automation proceeds at slowdown speed. When the automation reaches the opening mechanical stop give a Step-by-Step command (SS). In this phase the display shows LOP.</p>	
9.	<p>The automation moves in closing at running speed with slowdowns set.</p>	

**WARNING** - in the event of a safety device intervention, the learning is stopped and will appear on the display L--.

Press the "SS" button to start again the learning from the 4th point.